

Restrictive fire seals and the pattress solution

Some fire seals in walls can be restrictive, so it is difficult to insert the different pieces of the Protecta FR Board. Therefore Polyseam has tested a pattress system, where the boards are installed on the surface of the wall instead of inside the aperture. This is then an additional way of fixing the boards, but the fire classifications will still be limited to the different services given in this handbook, for drywalls with the system 2 x 50mm 1-S. Furthermore, any FR Pipe Wraps must be included.

There are two ways the pattress system can be installed, as follows:

